

## 4-2-1 1 Chip

Part No.	V <sub>RM</sub> (V)	I <sub>F</sub> (A)	I <sub>FSM</sub> (A)	t <sub>rr(1)</sub> (μS)	t <sub>rr(2)</sub> (μS)	Package	Fig. No.
EU 2YX	100	1.2	25	0.2	0.08	Axial(E1)	3
RU 2YX		1.5	30	0.2	0.08	Axial(R1)	4
RU 3YX		2.0	50	0.2	0.08	Axial(R2)	5
RU 4Y		3.5	70	0.4	0.18	Axial(R4)	7
RU 30Y		3.5	100	0.4	0.18	Axial(R3)	6
RU 4YX		4.0	100	0.4	0.18	Axial(R4)	7
FMU-G2YXS		10.0	100	0.2	0.08	TO-220F-2Pin	8
EU01Z		0.25	15	0.4	0.18	Axial(E0)	2
EU 1Z		0.25	15	0.4	0.18	Axial(E1)	3
AU01Z		0.5	15	0.4	0.18	Axial(A0)	1
RF 1Z	200	1.0	15	0.4	0.18	Axial(R1)	4
AS01Z		0.6	20	1.5	0.6	Axial(A0)	1
EH 1Z		0.6	30	4.0	1.3	Axial(E1)	3
RH 1Z		0.6	35	4.0	1.3	Axial(R1)	4
ES 1Z		0.7	30	1.5	0.6	Axial(E1)	3
ES01Z		0.7	30	1.5	0.6	Axial(E0)	2
AU02Z		0.8	25	0.4	0.18	Axial(A0)	1
EU02Z		0.8	15	0.4	0.18	Axial(E0)	2
EU 2Z		1.0	15	0.4	0.18	Axial(E1)	3
RU 2Z		1.0	20	0.4	0.18	Axial(R1)	4
RU 4Z	400	3.5	70	0.4	0.18	Axial(R4)	7
RU 30Z		3.5	80	0.4	0.18	Axial(R3)	6
EU01		0.25	15	0.4	0.18	Axial(E0)	2
EU 1		0.25	15	0.4	0.18	Axial(E1)	3
RU 1		0.25	15	0.4	0.18	Axial(R1)	4
AU01		0.5	15	0.4	0.18	Axial(A0)	1
RF 1		0.6	15	0.4	0.18	Axial(R1)	4
AS01		0.6	20	1.5	0.6	Axial(A0)	1
EH 1		0.6	30	4.0	1.3	Axial(E1)	3
RH 1		0.6	35	4.0	1.3	Axial(R1)	4
ES01	400	0.7	30	1.5	0.6	Axial(E0)	2
ES 1		0.7	30	1.5	0.6	Axial(E1)	3
AU02		0.8	25	0.4	0.18	Axial(A0)	1
EU02		0.8	15	0.4	0.18	Axial(E0)	2
EU 2		1.0	15	0.4	0.18	Axial(E0)	2
RU 2M		1.0	15	0.4	0.18	Axial(E1)	3
RU 3		1.1	20	0.4	0.18	Axial(R1)	4
RU 3M		1.5	20	0.4	0.18	Axial(R2)	5
RU 30		1.5	50	0.4	0.18	Axial(R2)	5
RU 4		2.0	200	0.4	0.18	Axial(R3)	6
RU 31	600	3.0	50	0.4	0.18	Axial(R4)	7
RU 4M		3.0	150	0.4	0.18	Axial(R3)	6
EU01A		3.5	70	0.4	0.18	Axial(R4)	7
EU 1A		0.25	15	0.4	0.18	Axial(E0)	2
RU 1A		0.25	15	0.4	0.18	Axial(E1)	3
AU01A		0.5	15	0.4	0.18	Axial(R1)	4
RF 1A		0.6	15	0.4	0.18	Axial(R1)	4
AS01A		0.6	20	1.5	0.6	Axial(A0)	1
EH 1A		0.6	30	4.0	1.3	Axial(E1)	3
RH 1A		0.6	35	4.0	1.3	Axial(R1)	4
ES01A		0.7	30	1.5	0.6	Axial(E0)	2
ES 1A		0.7	30	1.5	0.6	Axial(E1)	3

Part No.	V <sub>RM</sub> (V)	I <sub>F</sub> (A)	I <sub>FSM</sub> (A)	t <sub>rr(1)</sub> : I <sub>R</sub> =I <sub>F</sub>		90% Recovery Point		
				t <sub>rr(2)</sub> (μS)	Part No.	V <sub>RM</sub> (V)	I <sub>F</sub> (A)	I <sub>FSM</sub> (A)
RS 1A	600	0.7	30	1.5	AU02A	0.8	25	0.4
AU02A		0.8	25	0.4	EU02A	1.0	15	0.4
EU02A		1.0	15	0.4	EU 2A	1.0	15	0.4
EU 2A		1.0	20	0.4	RU 2	1.1	20	0.4
RU 2		1.1	20	0.4	RU 2AM	1.1	20	0.4
RU 2AM		1.1	20	0.4	RU 20A	1.5	20	0.4
RU 20A		1.5	20	0.4	RU 3A	1.5	20	0.4
RU 3A		1.5	50	0.4	RU 3AM	2.0	200	0.4
RU 3AM		2.0	200	0.4	RU 30A	3.0	50	0.4
RU 30A		3.0	50	0.4	RU 4A	3.5	70	0.4
RU 4A	800	3.5	70	0.4	RU 31A	5.0	30	0.4
RU 31A		5.0	30	0.4	RU 4AM	5.0	30	0.4
RU 4AM		5.0	30	0.4	FMU-G16S	10.0	40	0.4
FMU-G16S		10.0	40	0.4	FMU-G26S	10.0	40	0.4
FMU-G26S		10.0	40	0.4	RU 1B	0.25	15	0.4
RU 1B		0.25	15	0.4	RF 1B	0.6	15	0.4
RF 1B		0.6	35	4.0	RH 1B	1.0	20	0.4
RH 1B		1.0	20	0.4	RS 1B	0.7	30	1.5
RS 1B		0.7	30	1.5	RU 2B	1.0	20	0.4
RU 2B	1000	1.0	20	0.4	RU 3B	1.1	20	0.4
RU 3B		1.1	20	0.4	RU 4B	3.0	50	0.4
RU 4B		3.0	50	0.4	RU 1C	0.2	15	0.4
RU 1C		0.2	15	0.4	RU 1C	0.6	35	4.0
RU 1C		0.6	35	4.0	RH 1C	0.8	20	0.4
RH 1C		0.8	20	0.4	RU 2C	1.5	20	0.4
RU 2C		1.5	20	0.4	RU 3C	2.5	50	0.4
RU 3C		2.5	50	0.4	RU 4C	1.0	60	4.0
RU 4C		1.0	60	4.0	RH 2D	1.5	50	0.4
RH 2D	1500	1.5	50	0.4	RH 4D	2.5	50	0.4
RH 4D		2.5	50	0.4	ES01F	0.5	20	1.5
ES01F		0.5	20	1.5	ES 1F	0.8	60	4.0
ES 1F		0.8	60	4.0	RH 10F	1.0	60	4.0
RH 10F		1.0	60	4.0	RH 2F	1.0	60	4.0
RH 2F		1.0	60	4.0	RP 3F	2.0	50	0.7
RP 3F		2.0	50	0.7	RS 3FS	2.0	50	2.0
RS 3FS		2.0	50	2.0	RH 4FS	2.5	50	1.0
RH 4FS		2.5	50	1.0	RH 3F	2.5	50	4.0
RH 3F		2.5	50	4.0	RH 4F	2.5	50	4.0
RH 4F	10.0	2.5	50	4.0	FMQ-G1FS	5.0	50	0.7
FMQ-G1FS		5.0	50	0.7	FMQ-G2FS	5.0	50	0.5
FMQ-G2FS		5.0	50	0.5	FMQ-G2FMS	5.0	50	0.25
FMQ-G2FMS		5.0	50	0.25	FMQ-G5FMS	5.0	50	0.5
FMQ-G5FMS		5.0	50	0.5	FMU-G2FS	5.0	50	0.25
FMU-G2FS		5.0	50	0.25	FMQ-G2FLS	5.0	50	1.2
FMQ-G2FLS		5.0	50	1.2	RH 3G	1600	2.5	50
RH 3G		1600	2.5	50	4.0	4.0	1.3	Axial(R3)
4.0	1800	10.0	50	0.5	FMQ-G5GS	1700	10.0	50
FMQ-G5GS		10.0	50	0.5	FMP-G5HS	8.0	50	1.0
FMP-G5HS		8.0	50	1.0	FMR-G5HS	10.0	50	1.8
FMR-G5HS	2000	10.0	50	1.8	RC 2	2000	0.2	20
RC 2		2000	0.2	20	4.0	4.0	1.3	Axial(R1)
4.0								4

## External Dimensions

- No. 1 Axial (A0)**

**No. 2 Axial (E0)**

**No. 3 Axial (E1)**

**No. 4 Axial (R1)**

**No. 5 Axial (R2)**

**No. 6 Axial (R3)**

**No. 7 Axial (R4)**

**No. 8 (TO-220F-2 Pin)**

**No. 9 (TO-3PF-2 Pin)**

a. Part No.  
b. Polarity  
c. Lot No.

(unit: mm)

(unit: mm)