

**Product Change Notification Number:** F09/2011

**Date:** 2011-10-28

**Title:** Ferroxfol EMI absorber sheet manufacturing location and I2NC change

**Reason for Change:**

- |  |                                  |                                    |
|--|----------------------------------|------------------------------------|
| <input type="checkbox"/> Production                        | <input type="checkbox"/> Product | <input type="checkbox"/> Packaging |
| <input checked="" type="checkbox"/> Manufacturing Location | <input type="checkbox"/> Quality | <input type="checkbox"/> Material  |
| <input type="checkbox"/> Other                             |                                  |                                    |

**List of Products Subjected to Change:**

12NC	Reference	12NC	Reference
435000000421	FXF85/55/1-5T1	435000000151	FXF150/150/0.5-5R1
435000000331	FXF63/13/1-5T1	435000000231	FXF150/150/0.5-5F1
435000000021	FXF50/50/1-5W1	435000000041	FXF100/50/1-5W1
435000000261	FXF50/50/1-5T1	435000000281	FXF100/50/1-5T1
435000000101	FXF50/50/1-5R1	435000000121	FXF100/50/1-5R1
435000000181	FXF50/50/1-5F1	435000000201	FXF100/50/1-5F1
435000000011	FXF50/50/0.5-5W1	435000000031	FXF100/50/0.5-5W1
435000000251	FXF50/50/0.5-5T1	435000000271	FXF100/50/0.5-5T1
435000000091	FXF50/50/0.5-5R1	435000000111	FXF100/50/0.5-5R1
435000000171	FXF50/50/0.5-5F1	435000000191	FXF100/50/0.5-5F1
435000000411	FXF43/13/1-5T1	435000000061	FXF100/100/1-5W1
435000000451	FXF300/200/1-5T1	435000000301	FXF100/100/1-5T1
435000000471	FXF300/200/0.5-5T1	435000000141	FXF100/100/1-5R1
435000000081	FXF150/150/1-5W1	435000000221	FXF100/100/1-5F1
435000000321	FXF150/150/1-5T1	435000000051	FXF100/100/0.5-5W1
435000000161	FXF150/150/1-5R1	435000000291	FXF100/100/0.5-5T1
435000000241	FXF150/150/1-5F1	435000000131	FXF100/100/0.5-5R1
435000000071	FXF150/150/0.5-5W1	435000000211	FXF100/100/0.5-5F1
435000000311	FXF150/150/0.5-5T1		

**Change Description:** All the ferroxfol EMI absorber sheets (FXF), including references listed above, will change their manufacturing location (from Spain to Poland) and I2NC. The change will be effective from January 2012 onwards.

