



Flexible Cable Connectors

CDI Part No.	Cable Types
5730-1	RG 55, 58, 141, 142, 223, 303, 400
5730-2	RG 174, 188, 316, 179, 187



Straight Cable Male
(crimp or solder attachment)



Refer to Assembly Instructions 107 and 108 on pages 91 and 92.

CDI Part No.	Cable Types
5720-1	RG 55, 142, 223, 400, 58, 141, 303
5720-2	RG 174, 188, 316, 179, 187



Straight Cable Female
(crimp or solder attachment)



Refer to Assembly Instruction 109 on page 93.

CDI Part No.	Cable Types
5721-1	RG 55, 58, 141, 142, 223, 303, 400
5721-2	RG 174, 188, 316, 179, 187

Bulkhead Feedthrough Cable Female
(crimp or solder attachment)





Refer to Assembly Instruction 110 on page 94.

CDI Part No.	Cable Types
5851-1CC	RG 55, 58, 141, 142, 223, 303, 400
5851-2CC	RG 174, 188, 316, 179, 187


Center conductor is captivated.

Right Angle Cable Male
(crimp or solder attachment)



Refer to Assembly Instruction 101 on page 85.


Standard units are gold plated. Add suffix SF to Part Number for stainless steel finish.



CDI Part No.	Cable Types
5750-1CC	RG 55, 58, 141, 142, 223, 303, 400
5750-2CC	RG 174, 179, 187, 188, 316

Center conductor is captivated

Refer to Assembly Instruction 116 on page 100.



CDI Part No.	Cable Types
5752-1CC	RG 55, 58, 141, 142, 223, 303, 400
5752-2CC	RG 174, 179, 187, 188, 316

Center conductor is captivated

Refer to Assembly Instruction 121 on page 105.